

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



<u>WORK ORDER INFORMATION</u>

Work Order Name: WO/80008KN0691/1

Work Order Type: Weatherization

Audit Name: 80008KN0691-Audit

CLIENT INFORMATION

Client Name:

Address:

Client ID: 80008KN0691

Alt. Client ID: KNOX

AGENCY INFORMATION

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

Home built in 1950

An EPA Certified Firm/Renovator is required.

Client Name:

Client ID: 80008KN0691 Alt. Client ID: KNOX Work Order (Bid Form)

Work Order Name: WO/80008KN0691/1

Report Run On: 5/8/2010

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 15

Measures

		oken Pane (upto 10 squar FOUNDATION WINDOWS		ΥT	Componen	ts			Inspected	
C	Comment Refer t Field G	o Appendix A- Standards f Juide.	or Weath	erizati	on Materials	and Sou	theast			
					Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Windows	Broken Pane (upto 10 square feet)	Each	3						
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.								
2	Labor	Labor	Each	3						
(Other Detail									
				Measu	re Sub Total: [Sub Total:		
	Field Notes:									

Measure 2	Broken Pane (upto 10 squar feet)S1,S2,W4)	'e		Component	's			Inspected
	fer to Appendix A- Standards f eld Guide.	or Weath	erizatio	on Materials	and Sou	ıtheast		
				Estimated			Actual	
# Material / Lal	oor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Broken Pane (upto 10 square feet)	Each	1					
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	Labor	Each	1					
Other Detail								
							, and the same of	
		-	Measur	e Sub Total:			Sub Total:	
Field Notes:								

Report Run On: 5/8/2010

1	Measure 3 Ce	iling Repair 16 sq ft			Component	s			Inspected
С	confori	repair should include all in to the existing walls like natch as close as possible	eness. (Pa					s	
	Refer t	o Appendix A- Standards	for Weath	erizatio	on Materials : Estimated	an		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecified	Ceiling Repair (+)	SqFt	16					
2	Labor	labor	SqFt	16					
	Other Detail								
				Measur	e Sub Total:			Sub Total:	
Times.	Fleid Notes:								-

Measure	4 Mast	ic the Return Box(QTY	2)		Component	ts			Inspected
Commen	Use foar return boallowed.	hite Mastic to be applied to m board around edges to ox where it meets return r Refer to Appendix A- Sta st Field Guide.	fill in any egister w	voids ith app	and mastic. ropriate cau	Seal fro lk. No cl	nt of nanges		
					Estimated			Actual	
# Material	/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Constru	ction Mate	Mastic the Return Box	Each	1				The state of the s	
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor		Labor	Each	1					
Other Deta	11								
				Measur	e Sub Total:] ;	Sub Total:	
Field Not	es:								

Page 5 of 15

i	Measure 5 Mast	ic/insulate Supply Boo	ot(QTY 8)		Componer	its			Inspected
Liquid white Mastic to be applied to entire inside of boot to seal all seams. Top of boot where it meets subfloor to be caulked with appropriate caulk. Boots to be insulated on outside of boot to R-6. This is best performed with 2-part close cell foam. Location+Register Type^Initial (Pa) Dining RoomSupply2.1 Living RoomSupply0.1 Bdrm1Supply2.5 Bdrm2Supply2.6 KitchenSupply2.9 Bdrm3Supply2.5 Bdrm4Supply3.4 HallwayReturn0.8									
	панмауг	Returno.o			Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Mate	Mastic/Insulate Supply Boot	Each	8					
2	Labor	Labor	Each	8					
C	Other Detail								,
L									
			/	Measure	Sub Total:		:	Sub Total:	
	Field Notes:								

Page 6 of 15

Measure	6 Pre	hung Metal Door Unit(D2)		Componen	ts			Inspected
Comment	unit. A hinges, color to homeow Append	e old door before installing door is inclusive of weather threshold, facing, strike place chosen by homeowner wner desire height), caulk, lix A- Standards for Weath All keys given to home ow	rstripping ate, trim, or sand nailers. I erization	j, door jambs /staine Vo cha Materi	lock, deadbo , paint(1st q d/seal), peep nges allowed als and Sou	olt, door uality sei hole (at d. Refer	stop, nigloss : to		
					Estimated			Actual	
# Material /	/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors		Prehung Metal Door Unit	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor		Labor	Each	1					
Other Detail	11								
				Measur	e Sub Total:			Sub Total:	
Field Not	98:								

Measure	7		dow Glazing 32S3,N3,W3,W4,W5,W2	(QTY8)		Componen	ts			Inspected
Comment	Ne	w gla	e glazing must be 100% o zing should be even, sm dards for Weatherization	ooth, and	all lool	k uniform. Re	efer to A	ppendix	(
		TE: S cepta	Silicone, caulk, or any otl ble.	her produc	t that	s not windov Estimated		j is not	Actual	
# Material /	'Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows			Window Glazing	Each	8]		
			Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.					. F L	J E	L
2 Labor			Labor	Each	8					
Other Deta	il		processing .			, <u>, , , , , , , , , , , , , , , , , , </u>		-1.		
			The state of the s							
		,								
					Measui	e Sub Total:			Sub Total:	
Field Note	es:	, , ,				To the second se				

Measure 8 DWH Pipe Insula	ition		Componen	I	Inspected			
Comment								
			Estimated		Actual			
# Material / Labor Description /	Comment Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation DHW Pipe In	sulation Each	1						
Includes labo corners must properly. Ref Appendix A- for Weatheriz Materials and Field Guide.	be cut er to Standards zation					l and a second		
2 Labor DHW Pipe In	sulation Each	1						
Other Detail								
		Measu	re Sub Total:] ;	Sub Total:		
Field Notes:								

Report Run On: 5/8/2010

	Measure 9 W	all Insulation			Componen		5,WAL L 7,W		Inspected
C	Contr Contr instal interio up ar	des labor cost. Contractor reactor must dense pack insu- actor's responsibility to installing wall insulation. Contractor or exterior if needed while ea around house and clean and x A- Standards for Weat e.	ulation at 3 all wood o otor's resp e installing siding off	3.5 pou or Styro oonsibili g wall ir after n	nds per squa foam plugs i ity to repair v nsulation. Co neasure com	are foot. in holes a wall dama ontractor npleted. F	after age to clea Refer to		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	379.8					
2	Labor	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	379.8		and the second s			
(Other Detail								
ſ					***************************************				
				Measur	e Sub Total:			Sub Total:	
	Field Notes:						•		

C		attic spa access. soffit and insulatin silicone access a Grade 1	Lace showing depth of insulation. Build insulation dam around attic linstall baffles as needed to prevent loose fill insulation from entering discovering vent. Seal all holes, gaps, and penetrations in attic before ag. Seal around chimney with sheet metal and high temperature or fire resistant foam. Install R-30 fiberglass batt secured to attic and weather strip with foam tape. Contractor to install using Resnet Standards. Refer to Appendix A- Standards for Weatherization is and Southeast Field Guide. Estimated Actual Description / Comment Units Oty Unit Cost Total Oty Unit Cost Oty Oty Unit Cost Oty Unit Cost Oty Oty									
						Estimated	<i>t</i>		Actual			
#	Material /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total		
1	Insulation	1	Attic Insulation - Blown Fiberglass - R-19	SqFt	120	Tools and the second se						
2	Labor		Attic Insulation - Blown Fiberglass - R-19	SqFt	120							
(Other Detail											
			Programme									
			OF THE PROPERTY OF THE PROPERT							THE STREET OF PARTICULAR AND ADDRESS OF THE STREET		
					Measur	e Sub Total:			Sub Total:			
	Fleld Note	s:										

Components A1

Client ID: 80008KN0691 Alt. Client ID: KNOX

Measure 10 Attic Ins. R-19

Inspected

4	Measure 11 Wal	I Insulation		Components WALL 1,WALL 2,WALL 3,WALL 4							
C	Contrac Contrac installing interior o up area	es labor cost. Contractor notor must dense pack insuctor's responsibility to instag wall insulation. Contractor exterior if needed while around house and clean lix A- Standards for Weath	ulation at 3 all wood o ctor's resp e installing siding off	3.5 pou or Styro onsibili o wall in after m							
					Estimated			Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total		
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	901.2							
2	Labor	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	901.2							
C	Other Detail										
	- 107/2										
	None and the second	,	,	Measure	e Sub Total:]	Sub Total:			
	Field Notes:			***************************************		*** ***********************************					

Client ID: 80008KN0691 Alt. Client ID: KNOX

Page 12 of 15

Measure 12 DWH Tank Insulation			Components				Inspected			
C	omment									
					Estimated	1			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	-	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1			7			
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.					J (
2	Labor	DHW Tank Insulation	Each	1						-
		extend pressure relief pipe as needed) [.			
C	Other Detail									
	***************************************					***************************************				
				Measui	e Sub Total:]		Sub Total:	
	Fleld Notes:				77 TO THE THE TOTAL TO THE TOTAL THE TOTAL TO THE TOTAL TOTAL TO THE T					

Measure 13 CO	Monitor is Needed			Component	ts			Inspected
Comment Refer to Field Gu	Attachment A- Standard uide.	ds for Wea	theriza	ation Materia <i>Estimated</i>	ls and So	outheas		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Actual Unit Cost	Total
Health and Safety		Each	1		, ota,	Qiy	Om Cost	i Otai
Trouis and Galoty	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.	244	,	<u> </u>		and the state of t		
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
(Wal Comment A Certifi	ctice Lead Safe Weathe lls) ed Firm /Renovator is recopy of Lead Report and	quired to a			rules. N			Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	EPA RRP Lead Rules	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Vieasur	e Sub Total:		S	Sub Total:	
Field Notes:								

Client Name:

Client ID: 80008KN0691 Alt. Client ID: KNOX Work Order (Bid Form)

Work Order Name: WO/80008KN0691/1 Report Run On: 5/8/2010 DOE Weatherization Assistant

Version 8.6.0 Page 14 of 15

		Work Order Grand Total:	Grand Total	,
Mork Order Grand Total: Crand Total:				
Work Order Grand Total: Grand Total:	Work Orger Grand Lotal: Grand Total:			
Work Order Grand Total: Grand Total:	Work Order Grand Total: Grand Total:			
Work Order Grand Total: Grand Total:	work Order Grand Total: Grand Total:			
Work Order Grand Total: Grand Total:	Work Order Grand Total: Grand Total:			

Client Name:

Client ID: 80008KN0691 Alt. Client ID: KNOX Work Order (Bid Form)

Work Order Name: WO/80008KN0691/1 Report Run On: 5/8/2010